









DIN 913  
M10x45






M10




SCHNITT A-A



$\phi 6$

14


A



11

$\phi 14$


R114,17




R0,80







0,50 X 45°






0,50 X 45°










$\phi 52$














SCHNITT G-G



4	60250-XXX Teil5	1
5	60250-XXX Teil6	1
6	DIN 914 M5x4	1
7	DIN 913 M10x45	1
8	60250-V4A Teil3	1

