

$\varnothing 12,50$

M8

9

40,18

19,68

R2

3°


3








1








3,50


$\varnothing 4,20$

$\varnothing 30$









SCHNITT C-C

