






























SCHNITT A-A




















4	120-M20 Teil4	1
5	120-M20 Teil5	1
6	120-M20 Teil6	1

